

## Status of River Breakages Along Juba River , Somalia, March 2019

Region	District	Nearest Settlement	Latitude	Longitude	Comment	Status	Length (m)	Latest Image Date	Side of river bank facing downstream
Middle Juba	Saakow	Sakow	1.65977	42.42653	There is a breakage at this point. There is evidence of recent flooding as at Dec 2018. Still open as of 27 Feb 2019	Open	12	27-Feb-19	Left
Middle Juba	Saakow	Hilo Amin	1.64711	42.43286	There is a breakage at this point. There is evidence of some recent flooding as at Dec 2018. No evidence of intervention done as of 27 Feb 2019	Open	5	27-Feb-19	Right
Middle Juba	Saakow	Sakow	1.64510	42.43409	There is evidence of some recent flooding as at Dec 2018 due to low embankments. We can consider it as an open as it used to irrigate the nearby farms	Open	4	27-Feb-19	Left
Middle Juba	Saakow	Buurtule	1.51606	42.43539	There is a breakage at this point as seen on the image of 31 October. As of 19 Feb 2019 no intervention noticed.	Open	7	19-Feb-19	Left
Middle Juba	Saakow	Kadaarow	1.61342	42.43712	There is no evidence of recent flooding at this point as at Dec 2018 but there is an opening that can cause flooding should the river levels rise as of 27 Feb 2019.	Open	8	27-Feb-19	Right
Middle Juba	Saakow	Qaboobe	1.55097	42.44715	There is evidence of recent flooding in the nearby farms coming from an opening at this point as at Dec 2018. The image of 19 Feb 2019 shows no intervention.	Open	5	19-Feb-19	Right
Middle Juba	Bu'aale	Nadariis	1.40717	42.45307	The point has a breakage and there is no evidence of intervention as at 23 Jan 2019.	Open	8	23-Jan-19	Left
Middle Juba	Bu'aale	Gola	1.38101	42.46302	The point has a breakage and there is no evidence of intervention as at 23 Jan 2019.	Open	3	23-Jan-19	Left
Middle Juba	Bu'aale	Gola	1.39193	42.46417	The point has a breakage and there is no evidence of intervention as at 23 Jan 2019.	Open	4	23-Jan-19	Left
Middle Juba	Bu'aale	Gola	1.26909	42.54303	There is no evidence of intervention to close the breakage at this point as at Jan 2019	Open	4	31-Jan-19	Left
Middle Juba	Bu'aale	Reebaay	1.26703	42.54954	Vegetation cover at this point hinders assessment but there is no evidence of intervention to close the breakage at this point as at Jan 2019	Open	6	31-Jan-19	Right

## Status of River Breakages Along Juba River , Somalia, March 2019

Region	District	Nearest Settlement	Latitude	Longitude	Comment	Status	Length (m)	Latest Image Date	Side of river bank facing downstream
Gedo	Doolow	Bantaal	4.17834	42.11258	There is evidence of water spillage at this point and no evidence of any intervention.	Open	10	24-Jan-19	Left
Gedo	Doolow	Dollow	4.16217	42.07351	This is a canal intake used for irrigation into the nearby farms. There is no evidence of recent flooding nor of any interventions done.	Open	10	24-Jan-19	Right
Middle Juba	Jilib	Libaanga	0.47916	42.75655	There is a breakage at this point that has caused flooding in the nearby farms about 520m away as at 27 Feb 2019.	Open	22	27-Feb-19	Left
Middle Juba	Bu'aale	Bidi	0.98330	42.62334	This is an open breakage with no evidence of any intervention as at Dec 2018	Open	7	8-Dec-18	Left
Middle Juba	Bu'aale	Afgooy	0.95699	42.61649	This point is a canal intake and there is no evidence of intervention as at Dec 2018.	Open	6	8-Dec-18	Left
Middle Juba	Bu'aale	Mashane	0.82293	42.66119	The point is covered with vegetation but there is an opening here with no evidence of any intervention.	Open	6	8-Dec-18	Left
Middle Juba	Jilib	Wagadey	0.68750	42.69823	There is a breakage at this point with evidence of water spillage from the point as at 08 Dec 2018.	Open	21	8-Dec-18	Right
Lower Juba	Jamaame	Moofa	0.16010	42.74031	Vegetation hinders the assessment of the breakage at this point but there is no evidence of any intervention as at Feb 2019.	Open	10	12-Feb-19	Right
Middle Juba	Jilib	Ankele	0.40882	42.74364	There is no evidence of recent flooding at this point as at Mar 2019 but the point should be monitored because there is no evidence of intervention since the flooding that occurred in June 2018.	Open	34	3-Mar-19	Left
Middle Juba	Jilib	Seylac	0.55952	42.74371	There is no evidence of recent flooding as at Feb 2019 but there is an opening at this point.	Open	4	12-Feb-19	Left
Middle Juba	Jilib	Shangal Duniya	0.38863	42.74703	There is no evidence of recent flooding at this point as at Feb 2019. The point is covered with vegetation that hinders assessment of the opening but there is no evidence of intervention.	Open	14	12-Feb-19	Left

## Status of River Breakages Along Juba River , Somalia, March 2019

Region	District	Nearest Settlement	Latitude	Longitude	Comment	Status	Length (m)	Latest Image Date	Side of river bank facing downstream
Middle Juba	Jilib	Shangal Duniya	0.38851	42.74781	There is no evidence of recent flooding at this point as at Feb 2019. The point is covered with vegetation that hinders assessment of the opening but there is no evidence of intervention.	Open	10	12-Feb-19	Left
Middle Juba	Jilib	Shangal Duniya	0.39808	42.75167	There is a breakage at this point as noted in the image of 12 February 2019.	Open	24	12-Feb-19	Left
Lower Juba	Jamaame	Maama	0.16115	42.75583	There is no evidence of recent flooding at this point but there is a breakage as noted in the image of 12 February 2018.	Open	6	12-Feb-19	Left
Lower Juba	Jamaame	Makalaago	0.25657	42.75665	There is no evidence of recent flooding at this point but there is a breakage as noted in the image of 12 February 2018.	Open	4	12-Feb-19	Right
Middle Juba	Jilib	Muuna	0.50986	42.76413	There is no evidence of recent flooding at this point as at Feb 2019 but the point has an opening with no evidence of intervention.	Open	22	12-Feb-19	Left
Lower Juba	Jamaame	Makalaago	0.25696	42.76473	There is a breakage at this point as noted in the image of 12 February 2019.	Open	22	12-Feb-19	Right
Middle Juba	Jilib	Madhooka	0.55243	42.76525	There is no evidence of recent flooding but the point has an opening that is partly covered with vegetation.	Open	7	12-Feb-19	Left
Middle Juba	Jilib	Nasiib Buundo	0.34200	42.76738	There is no evidence of recent flooding at this point as at Feb 2019 but there is a breakage at this point as noted in the image of 12 February 2019.	Open	4	12-Feb-19	Right
Middle Juba	Bu'aale	Nadariis	1.40597	42.45478	The point has a breakage even though it is covered with vegetation and there is no evidence of intervention as at 23 Jan 2019.	Open	5	23-Jan-19	Left
Middle Juba	Bu'aale	Cismaan yarow	1.22632	42.55886	Vegetation cover hinders assessment of the embankment but the point neither shows evidence of recent flooding nor of any intervention as at Jan 2019.	Open	13	31-Jan-19	Left
Middle Juba	Saakow	Qaboobe	1.55013	42.44187	There is evidence of recent flooding from the opening at this point. There is need for intervention because there is no evidence of any intervention since the flooding of June 2018.	Open	5	28-Feb-19	Right

## Status of River Breakages Along Juba River , Somalia, March 2019

Region	District	Nearest Settlement	Latitude	Longitude	Comment	Status	Length (m)	Latest Image Date	Side of river bank facing downstream
Middle Juba	Jilib	Mareerey	0.43314	42.72693	There is no evidence of recent flooding at this point as at Mar 2019 but the point should be monitored because vegetation cover hinders assessment of the opening that caused flooding in June 2018.	Open	17	3-Mar-19	Left
Middle Juba	Jilib	Ankele	0.41183	42.74498	There is no evidence of recent flooding at this point as at Mar 2019 but the point should be monitored because vegetation cover hinders assessment of the opening that caused flooding in June 2018.	Open	38	3-Mar-19	Left
Lower Juba	Jamaame	Sunguuni	0.00487	42.66008	This is an opening created to allow water passage for irrigation.	Open	2	19-Feb-19	Right
Lower Juba	Jamaame	Malayle	-0.00490	42.65927	This is an opening created to allow water passage for irrigation.	Open	16	19-Feb-19	Left
Lower Juba	Jamaame	Malayle	-0.00450	42.65582	This is an opening and should be monitored because there is no intervention since the flooding of April 2018.	Open	16	19-Feb-19	Right
Lower Juba	Jamaame	Jibey	-0.01124	42.65797	This is an opening and should be monitored because there is no intervention since the flooding of June 2018.	Open	5	19-Feb-19	Right
Lower Juba	Jamaame	Jibey	-0.01092	42.65899	This is an opening and should be monitored because there is no intervention since the flooding of June 2018.	Open	14	19-Feb-19	Right
Lower Juba	Jamaame	Jibey	-0.01305	42.66592	This is an opening and should be monitored because there is no intervention since the flooding of April 2018.	Open	4	24-Feb-19	Left
Lower Juba	Jamaame	Juwaaley	-0.03572	42.61047	This is an opening and should be monitored because there is no intervention since the flooding of April 2018.	Open	5	27-Feb-19	Left
Lower Juba	Jamaame	Gaduud	-0.06089	42.59285	This is an opening and should be monitored because there is no intervention since the flooding of April 2018.	Open	10	27-Feb-19	Right
Lower Juba	Kismaayo	Gaduud	-0.07097	42.58780	This point has breakage as seen on the image of 27 Feb 2019.	Open	10	27-Feb-19	Right